



COMMANDE RAPIDE
SADDLE RAPID TRAVERSE

Vis et support
Screw and support

PI.60

VIS ET SUPPORT — SCREW AND BRACKET

PI. 60

Rep	N°	Désignation	Title	Rep	N°	Désignation	Title
110	436.195 à 198	Tôle de protection	Cover plate	121	436.133	Réglette	
111		Rondelle MU de 6	Washer MU 6	122		Vis HT 8×16	Screw HT 8×16
112		Vis CMH 6×16	Screw CMH 6×16	123		Vis CMH 10×35	Screw CMH 10×35
113	436.127	Réglette		124	436.175	Barre support	Bar bracket
114		Vis CMH 8×20	Screw CMH 8×20	125	436.176	Butée	Stop
115	436.187	Support	Bracket	126		Vis HT 10×20	Screw HT 10×20
116	436.124	Bague	Bush	127	436.130	Support	Bracket
117	436.096 à 099	Tige de traction	Drawbar	128		Bague Calcar 22×27×45	"Calcar" bush 22×27×45
118	436.102	Pion	Peg	129		Vis CMH 10×85	Screw CMH 10×85
119	436.129	Réglette		130	436.131	Flasque	Flange
120	436.126	Réglette		131		Vis CMH 8×16	Screw CMH 8×16
				132	436.104 à 108	Vis double pas	Double thread screw